Public Document Pack



County Offices Newland Lincoln LN1 1YL

20 November 2020

In accordance with the powers granted by the Local Authorities and Police and Crime Panels (Coronavirus) (Flexibility of Local Authority and Police and Crime Panel Meetings) (England and Wales) Regulations 2020 this will be a virtual meeting.

Flood and Water Management Scrutiny Committee

A meeting of the Flood and Water Management Scrutiny Committee will be held on **Monday, 30 November 2020 at 10.00 am as a Virtual - Online Meeting via Microsoft Teams** for the transaction of the business set out on the attached Agenda.

Access to the meeting is as follows:

Members of the Flood and Water Management Scrutiny Committee and officers of the County Council supporting the meeting will access the meeting via Microsoft Teams.

Members of the public and the press may access the meeting via the following link: https://lincolnshire.moderngov.co.uk/ieListDocuments.aspx?Cld=581&Mld=5529 where a live feed will be made available on the day of the meeting.

Yours sincerely

Debbie Barnes OBE Chief Executive

Marchanakin of the Flood and Water N

<u>Membership of the Flood and Water Management Scrutiny Committee</u> (11 Members of the Council and 7 Other Voting Members)

Councillors P A Skinner (Chairman), R P H Reid (Vice-Chairman), W J Aron, T R Ashton, Mrs A M Austin, Mrs P Cooper, A G Hagues, Mrs C J Lawton, C R Oxby, S R Parkin and C E Reid

Other Voting Members

District Councillors R Austin BEM (Boston Borough Council), P Vaughan (City of Lincoln Council), Mrs F M Martin MBE (East Lindsey District Council), Mrs L Hagues (North Kesteven District Council), M D Seymour (South Holland District Council), I G Fleetwood (West Lindsey District Council) and 1 Vacancy (South Kesteven District Council)

FLOOD AND WATER MANAGEMENT SCRUTINY COMMITTEE AGENDA MONDAY, 30 NOVEMBER 2020

ltem	Title	Pages
1	Apologies for Absence/Replacement Members	
2	Declarations of Members' Interests	
3	Minutes of the previous meeting held on 1 September 2020	5 - 10
4	Announcements by the Chairman, Executive Councillors and Lead Officers	
5	Investigations undertaken under Section 19 of the Flood and Water Management Act 2010 (To receive a report by Paul Brookes, Flood Risk Manager, which informs the Committee of the status of all current flood investigations being undertaken in the County)	
6	Environment Agency Update (To receive a report by Morgan Wray, Environment Agency, which updates the Committee on Environment Agency activities)	To Follow
7	Flood and Water Management Scrutiny Committee Work Programme (To receive a report by Tracy Johnson, Senior Scrutiny Officer, which enables the Committee to consider and comment on the content of its work programme to ensure that scrutiny activity is focused where it can be of greatest benefit)	

Democratic Services Officer Contact Details

Name: Rachel Wilson

Direct Dial **07796 994874**

E Mail Address <u>rachel.wilson@lincolnshire.gov.uk</u>

Please note: for more information about any of the following please contact the Democratic Services Officer responsible for servicing this meeting

- · Business of the meeting
- Any special arrangements
- Copies of reports

Contact details set out above.

All papers for council meetings are available on: https://www.lincolnshire.gov.uk/council-business/search-committee-records



PRESENT: COUNCILLOR P A SKINNER (CHAIRMAN)

Councillors R P H Reid (Vice-Chairman), W J Aron, T R Ashton, Mrs A M Austin, Mrs P Cooper, A G Hagues, Mrs C J Lawton, C R Oxby, C E Reid and R A Renshaw

District Councillors R Austin BEM (Boston Borough Council), P Vaughan (City of Lincoln Council), Mrs F M Martin MBE (East Lindsey District Council), Mrs L Hagues (North Kesteven District Council), M D Seymour (South Holland District Council) and I G Fleetwood (West Lindsey District Council)

External Agencies – Jonathan Glerum (Anglian Water) and Morgan Wray (Environment Agency)

Councillors C J Davie, D McNally and Eddy Poll (Executive Councillor, Commercial and Environmental Management), attended the meeting as observers

Officers in attendance:-

Steve Blagg (Democratic Services Officer), Paul Brookes (Flood Risk Manager), Richard Fenwick (County Highways Manager), David Hickman (Head of Environment) and Daniel Steel (Scrutiny Officer)

37 APOLOGIES FOR ABSENCE/REPLACEMENT MEMBERS

The Chief Executive reported that under the Local Government (Committee and Political Groups) Regulations 1990, she had appointed Councillor Mrs P Cooper to the Committee, in place of Councillor M Brookes, until further notice.

38 DECLARATIONS OF MEMBERS' INTERESTS

There were no declaration of interests to report at this stage of the meeting.

39 MINUTES OF THE PREVIOUS MEETING HELD ON 24 FEBRUARY 2020

RESOLVED

That the minutes of the previous meeting of the Committee held on 24 February 2020, be approved as a correct record and signed by the Chairman.

40 <u>ANNOUNCEMENTS BY THE CHAIRMAN, EXECUTIVE COUNCILLORS</u> AND LEAD OFFICERS

Councillor P A Skinner referred to the incidents of flash flooding which had taken place last week and stated that updates of these incidents would be reported to the Committee in due course.

Executive Councillor C J Davie, Economy and Place, stated that the Environment Agency had completed its 2020 beach nourishment programme; stated that following the completion of the River Steeping Action Plan, the County Council would support and maintain the main channels that fed in to the River Steeping around Wainfleet; stated the need to examine the Government's Planning White Paper and to work with partners in connection with the Defra review of surface flooding arising from the floods of 2019.

Councillor E J Poll stated that he was in attendance at today's meeting in his capacity as the Chairman of the England Northern Region Flood Council and had nothing to report.

41 <u>HIGHWAYS GULLY CLEANSING, REPAIR AND SURFACE WATER</u> FLOODING UPDATE

The Committee received a report in connection with the reactive, cyclic and planned aspects of highways drainage maintenance including the response to low-level flooding. The report gave details of statistics of highway assets including the annual budget; the use of technology to record data and incidents; the work of the local Highway Teams; the provision of updates to the public and an explanation of the capital programme.

Comments by Members included:-

- The responses to the public about flooding issues were clearer.
- There was still a backlog in dealing with reported flooding cases and more resources should be invested to address the backlog.
- Seasonal factors, the effects of tree roots and parked vehicles also caused gullies to be blocked.
- Some problems of blocked gullies were caused by utility companies. Officers stated that Members needed to report these incidents on the "Fix My Street" App. Officers agreed that coordination of utility activities could be further improved with the Council's Permitting Team having an important role in this area.
- The "targeted approach" by the use of new technology was welcomed as some gullies needed more attention than others.
- Reference was made to a specific and on-going flooding problem in the Kirton area, near Boston. Officers stated that this could be caused by a drainage capacity issue and it was agreed to speak to local officers and partners to examine this matter.

The report was welcomed by Members, who noted that rainfall events were more extreme nowadays and they hoped that resources would be targeted to the worse areas.

RESOLVED

- (a) That the report and comments made by Members be noted.
- (b) That the work being undertaken by the County Highways Service as detailed in the report be endorsed.

42 <u>ANGLIAN WATER PRESENTATION</u>

(Note: Councillor T R Ashton left the meeting during discussion of this item).

The Committee received a presentation from Anglian Water on their roles and responsibilities across Lincolnshire, including working with partners across the region to address flooding issues. The company covered a large and flat geographical area and used a lot of pumping stations to transport water. The industry was highly regulated and the three areas presenting challenges included climate change; population and economic growth and environmental protection.

Spending proposals by Anglian Water on drought and resilience had been referred to the Competitions and Markets Authority as Ofwat had objected to the proposals and a response was expected by Christmas 2020.

With regard to managing flood risk the main area of activity was addressing blockages with 80% of flooding caused by blockages, e.g. tree roots and oil/grease.

Tankers to carry water had been used last winter and Anglian Water was currently in discussions with the Environment Agency about how to address this issue in the future.

With regard to surface water management Anglian Water was examining the installation of larger pipes and green methods of storing water to prevent flooding.

Comments by Members included:-

- A Member enquired about whether the Asset Management Plan outcome would affect surface flooding issues in Tetney. Officers stated that while funding was available for Tetney it was not as much as had been hoped that there would be a positive outcome from the Competitions and Marketing Authority on Anglian Water's spending plans. Officers stated that there were some difficult issues taking place in Tetney and a wider discussion with the community was required and it was hoped to work with the National Flood Forum to help with communication with the local community to manage the issues in this area.
- An enquiry was made about flooding issues in properties in the Langwith area, east of Lincoln, especially as a new sewerage plant had recently been

constructed. Officers stated that the problems in this area were worse in the winter and they would examine the cause of the underlying issues.

• The use of combined service pipes caused flooding issues in some areas and did Anglian Water have a rolling programme to separate these pipes? Officers stated that Anglian Water did not have a rolling programme to separate the pipes. Anglian Water had a 25 year programme to address the problems caused by combined service pipes by means of water retention and to release water slowly so that the system was able to cope. It was hoped to more resilience to the system in the future as replacing existing pipes was very expensive.

RESOLVED

That the comments made by Members and the presentation be received and noted.

43 ENVIRONMENT AGENCY UPDATE

The Committee received an update report on Environment Agency activities, in relation to the effects of COVID-19, the on-going delivery of the capital programme and the recovery programme. Progress of individual projects was outlined, including, amongst others, the Boston Barrier, Stamp End (Lincoln) and beach nourishment programme on the east coast.

Comments by Members included:-

- There was still a lot of work to be done at Barlings Eau following serious flooding last year and it was hoped to see the bunding and piling completed by November 2020. Officers stated that more work was required at Barlings Eau and maintenance activities in the Billinghay catchment area, in consultation with the Internal Drainage Board, were taking place as there were areas of common interest.
- There were a lot of weeds in the River Witham at Stamp End, Lincoln. Officers agreed to investigate and report back to the Committee and added that there was extensive annual maintenance carried out in this area. Officers stated that a strategy for the lower Witham was being developed and consultants had been engaged starting with a consultation exercise.
- There was a need to treat water as a resource.

RESOLVED

- (a) That the comments by Members be noted and actioned where appropriate.
- (b) That the report and progress of the on-going delivery of the capital programme, be noted.

44 TO REPORT PROGRESS ON THE INVESTIGATIONS MADE IN THE COUNTY UNDER SECTION 19 OF THE FLOOD AND WATER MANAGEMENT ACT 2010 (FWMA)

The Committee received a standing report in connection with investigations undertaken in the County under Section 19 of the Flood and Water Management Act 2010. Officers stated that they were working through the backlog of cases detailed in the appendix of the report stating that many of the issues would be addressed before a Section19 report was completed.

Officers stated that flooding was normally caused by extreme water fall, e.g. thunderstorms, rather than the steady rainfall which had been experienced recently. Officers stated that they were aware of the flooding problems in Kirton and solutions were being investigated.

Officers stated that the County Council was working with its partners to examine surface water management and that it was important than the public continued to report flooding problems as only by reporting incidents could they be addressed by the Council and its partners.

Comments by Members included:-

- Details of those properties flooded at Kirton were provided with the properties being flooded many times.
- Officers stated that they would contact the District Councillor for East Lindsey
 District Council separately in connection with the issues raised in East
 Lindsey.

RESOLVED

- (a) That the comments by Members be noted and actioned where appropriate.
- (b) That the report and progress of investigations be noted.

45 2020+ STEEPING CATCHMENT ACTION PLAN UPDATE

The Committee received an update report in connection with the progress on the implementation of the recommendations for action detailed in the final report of the investigation into the flooding at Wainfleet in June 2019 which was presented to the Committee in February 2020.

The update was welcomed by Members as it was important to show the residents of Wainfleet that work was on-going to address the flooding problems in the town.

RESOLVED

That the report and progress on the recommendations as part of the Steeping Catchment Action Plan, be noted.

46 <u>FLOOD AND WATER MANAGEMENT SCRUTINY COMMITTEE WORK PROGRAMME</u>

The Committee received a report in connection with its Work Programme.

RESOLVED

That the Committee's Work Programme be agreed and updated accordingly.

The meeting closed at 12.00 pm



Open Report on behalf of Andy Gutherson, Executive Director – Place

Report to: Flood and Water Management Scrutiny Committee

Date: 30 November 2020

Subject: Investigations undertaken under Section 19 of the

Flood and Water Management Act 2010

Summary:

This is a standing item to inform the Committee of the status of all current flood investigations being undertaken in the County.

Actions Required:

Members of the Flood and Water Management Scrutiny Committee are invited to review and comment on the investigations undertaken in the County under Section 19 of the Flood and Water Management Act 2010.

Members are asked to view the current list of completed and active flood investigations online at https://www.lincolnshire.gov.uk/flood-risk-management/flood-investigations (a list of active investigations is also included at Appendix A) and inform Democratic Services in advance if they wish to raise any particular sites at the forthcoming Scrutiny Committee meeting.

1. Background

This is a standing item to inform the Committee on the position of all current Section 19 investigations in the County, which are listed in Appendix A. It will be noted that in some cases the investigation is marked as being completed, but the flood incident will remain on Appendix A. This is because there may be outstanding works arising from recommendations in the investigation report which have not yet been completed or programmed by the relevant Risk Management Authority as identified in Appendix A.

In the three-month period July to September 2020, rainfall in the County was reported by the Environment Agency to be normal to above normal on an east-west split, although August was a notably wet month with significantly higher than average rainfall across the County. The number of new flood investigations undertaken in August reflects this, as there were 15 Section 19 investigations started. Together with a couple of investigations initiated in September and a single

one in July, this brings the total for the last quarter to 18 and the total for the year from January to the end of October to 34.

2. Conclusion

Although not on the same scale as 2020, the year to date has already produced a higher than average number of flooding events that require a formal investigation. This high aggregate number over the last 18 months continues to be challenging to manage. However, the majority of flood investigations have been completed and good progress is being made in compiling and finalising the subsequent investigation reports with additional resource being brought in to address the back log.

3. Consultation

a) Risks and Impact Analysis

N/A

4. Appendices

These are liste	d below and attached at the back of the report						
Appendix A Active flood investigations							

5. Background Papers

No background papers within Section 100D of the Local Government Act 1972 were used in the preparation of this report.

This report was written by Paul Brookes, who can be contacted on 01522 553036 or paul.brookes@lincolnshire.gov.uk.

Appendix A

Duty to Investigate

Lincolnshire County C	Council Section 19 Investigations	s - West Lindsey District Counc	cil & City of Lincoln Council Network Area - Area High	nways Manager Jo	oe Phillips (Nort	h)														
Date of Incident	Town / Locality	Street / Road Name		Number Of Properties			Risk Management Authorities with Responsibilities and whether they are exercising functions	Date LCC Issued Recommendations to RMA's	Date RMA's Acknowledged Proposed Recommendations	Promoter	Works Status	Estimated Timescales Recommendation	Works Completion Date	LCC / District Council Work Status	EA Work Status	IDB Work Status	Water Company Work Status	3rd Party Work Status	S19 Report File Reference	New Network Area
28 June 2012	Keelby	Maple Avenue - DN41 8EN Pelham Crescent - DN41 8EW Riby Road - DN41 8ER	Surcharging surface water sewers combined with overland flows causing internal flooding.	4 Residential	Completed	Task 1 - Surface water drainage scheme under consideration. Further LCG investigation and design required. Feasibility 2022/2023, Work 2023/2024. Some A18 cut-off remedial work has been identified to have some mitigation benefit.	LCC - Yes	01/10/2013	26 September 2012	LCC AW	On-going	Investigation & Feasibility 2000/21 Possible works 2023/24. Potential Grant In Aid scheme.	Task 1 - TBC	On-going	NA	NA	On-going	NA	\$19-032	WLDC & CoLC
09 June 2014	Gainsborough	Caldicott Drive - DN21 1FJ Darwin Street - DN21 1DL Eisham Walk - DN21 1SU Hill Crescent - DN21 1RT Limber Close - DN21 1RT Limber Close - DN21 1TQ Marshalls 'Yard - DN21 2AU Priory Close - DN21 1DL Rectory Avenue - DN21 2JE Silver Street - DN21 2D Spring Gardens - DN21 2DC Trinly Street - DN21 2JD Longwood Road	Intense rainfall exceeded the capacity of the surface water drainage network, which caused the systems to surcharge, ultimately resulting in surface water runoff entering properties.	53 Residential & Commercial	Completed	Task 1-LCC has identified at least 5 schemes through feasibility studies and placed then on the national feasibility studies and placed then on the national factors. Task 2- Further feasibility work is required, which is ongoing. It is anticipated that construction could be started in 2024, subject to funding.	LCC - Yes WLDC - Yes STW - Yes	30/02/2015	20 February 2015	rcc	On-going	Feasibility 2021/22 Construction 2024/25	Task 1 - TBC Task 2 - TBC	Ongoing	NA	NA	NA	NA	S19-115	WLDC & CoLC
15 June 2016	Cherry Willingham	Ancaster Close - LN3 4JF	Drainage system resulted in internal flooding.	1 Residential	On-going	Awaiting report	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-164	WLDC & CoLC
15 June 2016 23 August 2017 15 January 2018 11 June 2019	Cherry Willingham	Lime Grove - LN3 4BD	Surface water flooding is believed to have resulted from inadequacies of two surface water drainage catchments; Lime Grove and Sycamore Close.	1 School	On-going	ТВС	LCC - Yes Witham 3rd IDB - Yes EA - Yes AW - Yes WLDC - Yes	26/07/2019 27/02/2020 28/05/2020 26/06/2020	Witham 3rd IDB - 01/06/2020 26/07/2019 27/02/2020 29/07/2020	TBC	On-going		TBC	ТВС	ТВС	ТВС	TBC	TBC	S19-201	WLDC & CoLC
10 August 2018	Lincoln	Percy Street - LN2 5ET	Deficiencies within the surface water drainage system serving Percy Street, coupled with the topography of the locality resulted in surface water flooding.	1 Residential	On-going	твс	LCC - Yes Witham 3rd IDB - Yes EA - Yes AW - Yes CoLC - Yes	26/07/2019 27/02/2020 28/05/2020 26/06/2020	TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-213	WLDC & CoLC
10 August 2018	Lincoln	Allenby Close - LN3 4RP	Surface water flooding at Allenby Close was a combination of the following factors: the topography of the estate roads; properly threshold levels; kerb heights; and blockages in the surface water drainage system.	1 Residential	Completed	Task 1 - CoLC consider undertaking the remedial works agreed between CoLC and the developer. Task 2 - Consideration be given to the cleansing of the existing quitiles and linear drainage systems. Task 3 - Consideration of adopting a cyclic cleansing strategy be considered.	LCC -Yes Witham 3rd IDB - Yes EA - Yes AW - Yes CoLC - Yes	15/08/2019	твс	NA	On-going	TBC	Task 1 - TBC Task 2 - TBC Task 3 - TBC	On-going	NA	NA	NA	On-going	\$19-214	WLDC & CoLC
11 June 2019	Cherry Willingham	Lime Grove - LN3 4BD	Surface water flooding is believed to have resulted from inadequacies of two surface water drainage catchments; Lime Grove and Sycamore Close.	1 School	On-going	ТВС	LCC - Yes Witham 3rd IDB - Yes AW - Yes EA - Yes WLDC - Yes	26/07/2019 27/02/2020 28/05/2020 26/06/2020.	26/07/2019 27/02/2020 29/07/2020	TBC	On-going	TBC	TBC	TBC	ТВС	TBC	TBC	TBC	S19-180	WLDC & CoLC
14 June 2019	Lincoln	High Street - LN5 7AF	Deficiencies within the surface water drainage system serving the commercial property, resulted in water ponding, which eventually flowed into the property. This is believed to be the most likely cause of flooding.	1 Commercial	On-going	TBC	LCC - Yes AW - Yes Upper Witham IDB - Yes EA - Yes CoLC - Yes	11/09/2020	Upper Witham IDB - 14/09/2020	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-233	WLDC & CoLC
18 June 2019	Lincoln	Alexandra Terrace - LN1 1JF	TBC	1 TBC	On-going	TBC	TBC	TBC	TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-244	WLDC & CoLC
27 July 2019	Lincoln	Welton Gardens - LN2 2AY	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-251	WLDC & CoLC
27 August 2019 28 August 2019	Brookenby	Dale View Road - LN8 6EP	Internal flooding to 2 domestic properties.	4 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-253	WLDC & CoLC
06 September 2019	Lincoln	Nettleham Close - LN2 1SJ	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-254	WLDC & CoLC
27/08/2019 11/02/2020	Lincoln	Sincil Street - LN5 7EJ	Flooding is believed to be a result of numerous factors: (a) deficiencies in the surface water drainage system; and (b) potential surface pavement misalignment, particularly on Norman Street. This results in flood flow paths bypassing gully locations and are not necessarily diverted away from the property.	1 Commercial	On-going	ТВС	LCC - Yes AW - Yes EA - Yes CoLC - Yes	15/04/2020 14/05/2020 08/06/2020 29/06/2020	Witham 3rd /1st IDB - 24/04/2020	TBC	On-going	TBC	TBC	ТВС	твс	твс	TBC	TBC	S19-266	WLDC & CoLC
15 October 2019	Lincoln	Manby Street - LN5 8NW	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-275	WLDC & CoLC
29 October 2019	Cherry Willingham	Waterford Lane - LN3 4AN Fiskerton Road - LN3 4AP	Internal flooding to 6 domestic properties.	6+ TBC	On-going	твс	TBC		TBC	твс	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-287	WLDC & CoLC
26 October 2019	Blyton	Station Road - DN21 3LE	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-289	WLDC & CoLC
26 October 2019	Scotter	Lindholme - DN21 3UR	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-290	WLDC & CoLC
9th August 2019	Bardney	Silver Street - LN3 5XG	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-293	WLDC & CoLC
11 November 2019 14 November 2019	Cherry Willingham	Fiskerton Road - LN3 4AP	Internal flooding to one domestic property.	1+ TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-305	WLDC & CoLC
08 November 2019	Saxilby	Sykes Lane - LN1 2NS	Internal flooding to one domestic property.	1 Residential	On-going	твс	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-306	WLDC & CoLC



Duty to Investigate Section 19 Investigat Lincolnshire County Council Section 19 Investigations - West Lindsey District Council & City of Lincoln Council Network Area - Area Highways Manager Joe Phillips (North) Risk Manag Date LCC Issue Date RMA's LCC / Distri EA Work Status IDB Work Status 3rd Party S19 Repor Description of Flooding exercising functions Date of Incident Town / Locality Street / Road Name Promoter Sincil Bank - LN5 8LD 1 Commercial TBC TBC TBC TBC S19-307 WLDC & CoLC 08 November 2019 Lincoln Internal flooding to one commercial property. On-going n-going 07 November 2019 Blyton Station Road - DN21 3LE Internal flooding to one domestic property. 1 Residential On-going TBC S19-309 WLDC & CoLC TBC TBC TBC S19-310 WLDC & CoLC On-going Station Road - DN21 3LE 1 Residential TBC S19-312 WLDC & CoLC 11 November 2019 Blyton On-going Internal flooding to one domestic property. On-going 2 Residential TBC TBC TBC TBC WLDC & CoLO 11 November 2019 Lincoln Lindum Avenue - LN2 5JB Internal flooding to two domestic properties. On-going TBC TBC TBC On-going TBC TBC TBC TBC S19-313 11 November 2019 Laughton Road - DN21 4TZ 1 Commercial TBC S19-314 WLDC & CoLC Snitterby Internal flooding to one commercial property. On-going On-going TBC TBC WLDC & CoLC 08 November 2019 Langworth Scothern Lane - LN3 5BH Internal flooding to one domestic property. 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC S19-317 08 November 2019 Kexby Kexby Lane - DN21 5PG Internal flooding to one domestic property. 1 Residential On-going TBC S19-318 WLDC & CoLC WLDC & CoLO Owmby Lane - LN7 6HE 1 Residential TBC TBC TBC TBC TBC TBC TBC TBC S19-319 08 November 2019 North Kelsey Moor Internal flooding to one domestic property. On-going TBC TBC On-going TBC TBC 08 November 2019 Willingham By Stow The Hop Gardens - DN21 5JT Internal flooding to one domestic property. 2 Residential TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC S19-320 WLDC & CoLC 8 - 10 TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-322 WLDC & CoLC 08 November 2019 Stainton By Langworth Scothern Lane - LN3 5BH TBC TBC Internal flooding to eight-ten domestic properties On-going On-going TBC TBC WLDC & Col C 08 November 2019 Waddingham Common Boad - DN21 4SY Internal flooding to one domestic property. 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC S19-323 07 November 2019 11 November 2019 Kexby Kexby Lane - DN21 5PG Internal flooding to a domestic property. 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-325 WLDC & CoLC 12 November 2019 Market Basen Dear Street - LN8 3BH 1 Residential On-going TBC S19-326 WLDC & CoLC 14 November 2019 St Andrews Drive - LN6 7UG Internal flooding to one domestic property. 1 Residential TBC S19-329 WLDC & CoLC On-going On-going 1 Residential TBC TBC TBC TBC TBC TBC WLDC & CoLC 20 November 2019 North Owersby Moor Road - LN8 3PR Internal flooding to one domestic property. On-going TBC TBC TBC On-going TBC TBC S19-334 TBC TBC WLDC & CoLC On-going 07 December 2019 Lindholme - DN21 3UR 7+ TBC On-going TBC S19-339 WLDC & CoLO 26 November 2019 Scotter Riverside - DN21 3UG Internal flooding to four domestic properties. 4+ TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-340 WLDC & CoLC 14 November 2019 Church Street - DN21 2JR 1 Commercial TBC S19-342 WLDC & CoLC Internal flooding to one commercial property. On-going On-going 06 December 2019 Market Basen Dear Street - LN8 3BH Internal flooding to one domestic property. 1 Residential On-going TBC S19-348 WLDC & CoLO TBC 27 June 2019 Lindum Terrace - LN2 5RT TBC TBC TBC TBC WLDC & CoLC Internal flooding to one domestic property. On-going On-going The flooding appears to be caused by rainfall, supplemented by highway urface water, flowing on the footpath and being deflected to the low poin which coincides with an off-let and the gate to the property. The ponded and, as the guily was blocked or otherwise not colecting the surface flow, water flowed towards the property and entered it. TBC TBC TBC TBC S19-361 WLDC & CoLO On-going Gainsborou EA - Yes Silver Street - LN3 5XG TBC TBC TBC TBC TBC TBC TBC S19-363 WLDC & CoLC 11 February 2020 1 TBC On-going TBC TBC TBC TBC Bardney Internal flooding to one property. On-going WLDC & CoLO 09 February 2020 Lincoln High Street - LN5 7DR Internal flooding to two properties 2 TBC On-going TBC S19-365 Lincoln Percy Street - LN2 5ET 1 Residential TBC S19-367 WLDC & CoLC On-going veen 10 November 201 19 November 2019 TBC TBC TBC TBC TBC TBC North Kelsey Moor Caistor Road - LN7 6HF Internal flooding to one property. 1 Residential On-going TBC TBC On-going TBC TBC TBC S19-379 WLDC & CoLC veen 10 November 201 19 November 2019 Gainsborough Ermine Street - DN21 4UB Internal flooding to one property. 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-380 WLDC & CoLC WLDC & CoLC Blyton Internal flooding to potentially 3+ properties 3 TBC On-going TBC S19-381 veen 10 November 2019 19 November 2019 TBC TBC TBC TBC TBC TBC TBC S19-382 WLDC & CoLC Market Rasen Dear Street - LN8 3BH Internal flooding to one property. 1 Residential On-going TBC TBC TBC On-going veen 10 November 201 19 November 2019 TBC 1 Residential TBC TBC TBC TBC TBC TBC S19-383 WLDC & CoLC Langworth Scothern Lane - LN3 5BH Internal flooding to one property. On-going TBC TBC TBC On-going TBC



Duty to Investigate Section 19 Investigati Lincolnshire County Council Section 19 Investigations - West Lindsey District Council & City of Lincoln Council Network Area - Area Highways Manager Joe Phillips (North) Risk Management Authorities with Responsibilities and whether they are exercising functions LCC / District Council Work Status Date LCC Issued Date RMA's EA Work Status IDB Work Status 3rd Party S19 Repor Work Status File Referen Date of Incident Town / Locality Street / Road Name Description of Flooding Proposed Action/Works Promoter 6 Residential TBC TBC TBC TBC TBC TBC TBC TBC S19-384 WLDC & CoLC Internal flooding to six properties On-going n-going veen 10 November 2019 19 November 2019 TBC TBC TBC TBC S19-385 WLDC & CoLC 2 Residential TBC TBC TBC TBC TBC TBC TBC Market Rasen Internal flooding to two properties. On-going On-going Honeyholes Lane - LN2 3SU Internal flooding to one property. 1 Residential On-going TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-386 WLDC & CoLC On-going een 10 November 201 19 November 2019 Cherry Willingham Waterford Lane - LN3 4AN 1 Residential On-going TBC S19-387 WLDC & CoLC veen 10 November 2019 19 November 2019 TBC TBC WLDC & CoLC Stow Ingham Road - LN1 2DG 1 Residential TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-388 Internal flooding to one property. On-going On-going On-going TBC TBC WLDC & CoLC veen 10 November 201 19 November 2019 North Kelsev Carr Road - LN7 6LG Internal flooding to one property. 1 Residential On-going TBC S19-391 WLDC & Col C A631 Bishopsbridge to A1103 - LN8 3LY 1 Residential TBC WLDC & CoLC Market Rasen Internal flooding to one property. On-going TBC On-going S19-394 Internal flooding to one property. 1 Residential TBC TBC TBC TBC TBC TBC TBC TBC S19-395 WLDC & CoLC Bishopbridge On-going On-going Market Rasen Bishop Norton Road Internal flooding to one property. 1 Residential On-going TBC S19-396 WLDC & CoLO n-going Redbourne Road Internal flooding to one property. 1 Residential On-going TBC S19-398 WLDC & CoLO On-going veen 10 November 201 19 November 2019 Waddingham Stainton Avenue Internal flooding to one property. 1 Residential On-going TBC S19-399 WLDC & CoLC veen 10 November 2019 19 November 2019 Sturton By Stow Internal flooding to three properties. 3 Residential On-going TBC S19-400 WLDC & CoLC On-going Kexby Lane - DN21 5PG Internal flooding to three properties. 3 Residential TBC On-going TBC S19-401 WLDC & CoLC een 10 November 2019 19 November 2019 Snitterby Carr Lane - DN21 4UU 1 residential TBC S19-402 WLDC & CoLC Snitterby On-going Internal flooding to one property. On-going veen 10 November 201 19 November 2019 TBC TBC WLDC & CoLC Nettleton Southwell Close - LN7 6NW Internal flooding to one property. 1 residential On-going TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-403 Fiskerton Road - LN3 4AP 1 residential TBC TBC TBC TBC TBC TBC TBC WLDC & CoLC On-going TBC WLDC & CoLC Scothern Lane - LN2 3QP 1 residential TBC S19-405 Dunholme Internal flooding to one property. On-going On-going veen 10 November 2019 19 November 2019 Lincoln Southdown - LN5 9UW Internal flooding to seven properties 7 Residential On-going TBC S19-406 WLDC & CoLC Faldingworth Road - LN8 2DF TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-407 WLDC & CoLC On-going On-going 11 June 2020 25 July 2020 Lincoln Sincil Street - LN5 7EJ TBC 1 TBC On-going TBC S19-413 WLDC & CoLC 16 August 2020 Lincoln Sincil Street - LN5 7EJ TBC 1 TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-414 WLDC & CoLC 17 August 2020 Market Rasen Oxford Street - LN8 3AL TBC 2 TBC On-going TBC S19-420 WLDC & CoLC Waterloo Street - LN8 3ES TBC TBC TBC TBC TBC 17 August 2020 On-going



Section 19 Investig Lincolnshire County		Investigations - East Lindse	y District Council Network Area - Area Highways Manager Rus	ssell Crockford (E	ast)															
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties		Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Date LCC Issued Recommendations to RMA's	Date RMA's Acknowledged Proposed Recommendations	Promoter	Works Status	Estimated Timescales Recommendation	Works Completion Date	LCC / District Council Work Status	EA Work Status	IDB Work Status	Water Company Work Status	3rd Party Work Status	S19 Report File Reference	New Network Area
28 June 2012	Horncastle	South Street - LN9 6EF Bull Ring - LN9 5HU	Heavy rainfall (estimated to be a 1 in 40 year event) caused overland and highway surface water flows to collect at the low area of the Bull Ring and South Street overwhelming the local surface water sewerage system; which was also suffering from surcharged outfalls due to high rive levels. Consequently resulting in three properties experiencing internal flooding.	3 Residential	Completed	Task 1 - LCC is to check and repair their guilles and system. Task 2 - Anglian Water is to check their surface water systems and consider improvement works in future asset management plans. Task 3 - Consideration should be given to an overall surface water study for Homcastle. Task 3 update - Estimated completion 2012/2022. Task 4 - LCC is to include additional minor works in the future works programme.	LCC - Yes AW - Yes		25 January 2013	LCC	On-going	2018/19	Task 1 - 01/09/2017 Task 2 - TBC Task 3 - TBC Task 4 - TBC	On-going	NA	NA	On-going	NA	S19-003	ELDC
28 June 2012	Horncastle	Langton Hill - LN9 5AH	Heavy rainfall (estimated to be a 1 in 40 year event) caused significant overland flows from the adjacent histoid and agricultural land, which was not contained by the interceptor dich. Combined overland and highway surface water overwhelmed both the highway and surface water sewer drainage systems on Langton Hill and West Street, and caused flooding at the bottom of the hill.	3 Residential	Completed	Task 1 - Highway drainage system repaired and functioning. Task 2 - Anglian Water checked the surface water system and it is working acceptably. Initial works delivered. Task 3 - Consideration should be given to an overall surface water study for Homcastle Task 3 update - Estimated competion 2021/2022. Task 4 - Witham 3rd Internal Drainage Board is ensuring that ditches are cleared by respective riparian land owners.	LCC - Yes AW - Yes Witham 3rd IDB - Yes		25 January 2013	LCC	On-going	2019/20	Task 1 - 05/07/2012 Task 2 - TBC Task 3 - TBC Task 4 - TBC	Completed	NA	Completed	On-going	NA	S19-004	ELDC
28 June 2012	New Bolingbroke	Main Road - PE22 6JE Station Row - PE22 7LB	Heavy rainfall (estimated to be a 1 in 40 year event) caused highway surface water flows to collect in the low area of Main Road/Station Row overwhelming the highway drainage system in the footway. Consequently resulting in seven properties experiencing internal flooding.	7 Residential	Completed	Task 1 - LCC removed dropped kerbs outside the post office and replaced them with full height kerbs. Task 2 - LCC investigation found the drainage system to be damaged by buildings/trees and a new outfall is required. Solution being designed and costed.	LCC - Yes		25 January 2013	NA	On-going	2014 - 2016	Task 1 - Completed (Date TBC) Task 2 - TBC	On-going	NA	NA	NA	NA	\$19-007	ELDC
28 June 2012	Toynton St Peter	Ings Lane - PE23 5AU	Overland flows surcharged a number of riparian watercourses in the area resulting in internal flooding to a low lying property in lngs Lane.	1 Residential	Completed	Task 1 - LCC have completed a feasibility report. An outline business case for FDGIA is being prepared for delivery of a scheme for 2021/2022.	Witham 4th IDB - Yes LCC - Yes		25 January 2013	LCC	On-going	Possible works 2021/22	Task 1 - TBC	On-going	NA	NA	NA	NA	S19-010	ELDC
09 June 2014	Skegness	North Parade - PE25 2TE	Intense rainfall caused drainage systems to surcharge resulting in surface water entering the property.	1 Commercial	Completed	Task 1 - After further investigations carried out by AW additional works are planned, including running of a new model.	LCC - Yes AW - Yes	Nov-14	30 October 2014	NA	On-going	1 March 2020	Task 1 - TBC	NA	NA	NA	On-going	NA	S19-101	ELDC
24 June 2014	Skegness	Sunningdale Close - PE251BA	Heavy rainfall exceeded the capacity of the local surface water drainage system, resulting in overland flows, which due to local topography lead to internal flooding of two properties.	2 Residential	Completed	Task 1 - Further investigations to be carried out by AW and Lindsey Marsh IDB to establish outfall. Task 2 - Anglian water removed gas service pipes intruding in the surface water system in 2015. Task 3 - Anglian Water consider investigating the surface water system for possible restrictions to flow. Task 4 - Anglian Water consider undertaking an analysis of the capacity of the surface water system.	LCC - Yes AW - Yes	07/10/2014	11 November 2014	NA	On-going	Spring 2015	Task 1 - TBC Task 2 - 2015 Task 3 - TBC Task 4 - TBC	NA	NA	On-going	On-going	NA	S19-098	ELDC
24 June 2014 13 July 2014	Skegness	Sunningdale Drive - PE25 1AU	Heavy rainfall exceeded the capacity of the local surface water drainage system, resulting in overland flows, which due to local topography lead to internal flooding of one property.	1 Residential	Completed	Task 1 - Further investigations to be carried out by AW, Lindsey Marsh IDB, LCC and ELDC.	LCC - Yes AW - Yes	01/11/2014	11 November 2014	NA	On-going	Spring 2015	Task 1 - TBC	On-going	NA	On-going	On-going	NA	S19-099	ELDC
24 June 2014	Skegness	Grand Parade - PE25 2UG	Heavy rainfall exceeded the capacity of the local surface water drainage system, resulting in overland flows, which due to local topography lead to internal flooding of one property.	1 Commercial	Completed	Task 1 - Further investigations to be carried out by AW & ELDC. Task 2 - AW to check new model.	LCC - Yes AW - Yes ELDC - Yes	01/11/2014	11 November 2014	NA	On-going	Spring 2015	Task 1 - TBC Task 2 - TBC	On-going	NA	On-going	On-going	NA	S19-100	ELDC
27 August 2016	Chapel St Leonards	The Esplanade - PE24 5TB	LPP used to remove large amount of water.	2 Commercial	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-195	ELDC
27 August 2016	Chapel St Leonards	St Leonards Drive - PE24 5UZ	Main pump used.	1 Commercial	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-196	ELDC
01 April 2018 02 April 2018 10 April 2018	Louth	Grimsby Road - LN11 0ED	Runoff from adjacent agricultural land resulted in the surcharging of the combined sewerage system, which ultimately resulted in internal property flooding due to surface water.	3 Residential	Completed	Task 1 - Consideration be given to identifying the ownership of the various unknown drainage assets in order to assign responsibility, provide appropriate maintenance. Task 2 - Consideration be given to ensuring the unknown drainage assets have an adequate connection to the AW and Highways nested to the AW and AW of the AW and AW of the AW of	LCC - Yes AW - Yes Lindsey Marsh IDB - Yes EA - Yes ELDC - Yes	18/06/2020 29/06/2020	6 October 2020	твс	On-going	TBC	Task 1 - TBC Task 2 - TBC Task 3 - TBC Task 4 - 10 January 2020	On-going	TBC	TBC	TBC	TBC	S19-199	ELDC
02 June 2018 27 July 2018 (Witham Road)	Woodhall Spa	Witham Road - LN10 6RA Tor-O-Moor Road - LN10 6TD	Heavy rainfall coupled with deficiencies within the existing drainage system resulted in internal property flooding at Witham Road. Flooding occurred on Tor-O-Moor Road due to deficiencies within the surface water drainage system.	3 Residential	On-going	TBC	LCC - Yes Witham 3rd IDB - Yes EA - Yes AW - Yes ELDC - Yes	15/08/2019	TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-203	ELDC
02 June 2018 11 June 2019 27 August 2019	Burgh on Bain	Main Road - LN8 6JY	Deficiencies within the highway surface water drainage system coupled with the road / footpath / access alignment enabled and directed surface water flows resulting in internal properly flooding.	1 Residential	On-going	Task 1 - Upon the request of ELDC, Ajet attended site and cleaned all the road guillies and jetted all outlets. Ajet also advised of issues with the pipework, which was passed on to LCC Highways.	LCC - Yes Witham 3rd IDB - Yes ELDC - Yes	18/06/2020 29/06/2020	19/06/2020 (ELDC) 01/07/2020 (Witham 3rd IDB)	TBC	On-going	TBC	Task 1 - TBC	ELDC - Completed	NA	TBC	NA	TBC	S19-204	ELDC
12 March 2018	Partney	Chapel Lane - PE23 4PY	The surface water flooding experienced in Chapel Lane was a result of the poor condition of the carriageway on Chapel Lane and inadequacies in the carriageways surface water drainage system.	1 Residential	Completed	Task 1 - LCC Highways consider undertaking a CCTV survey to inspect and assess the condition of the highway drainage system and usfall to the reparian watercourse. Task 2 - LCC Highways consider undertaking a hydraulic check of the system. Task 3 - LCC Highways consider the removal of vegetation around the burney of the condition of the condi	LCC - Yes Lindsey Marsh IDB - Yes EA - Yes AW - Yes ELDC - Yes	30/04/2019 26/06/2020	AW - 03/05/2019 EA - 01/05/2019 ELDC - 29/06/2020 LMIDB - 03/07/2020 LCC - 29/07/2020	твс	On-going	ТВС	Task 1 - TBC Task 2 - TBC Task 3 - TBC Task 4 - TBC Task 5 - TBC Task 6 - TBC	On-going	NA	NA	NA	NA	\$19-206	ELDC
27 July 2018	Skegness	Sunningdale Drive - PE25 1AU	Deficiencies within the surface water drainage system serving Sunningdale Drive is likely to be the causation of the property flooding experienced.	6 Residential	On-going	TBC	LCC - Yes AW - Yes Lindsey Marsh IDB - Yes EA - Yes ELDC - Yes	26/02/2020 28/05/2020 26/06/2020	10/03/2020 (except AW)	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	\$19-210	ELDC
27 July 2018	Horncastle	Churchill Avenue - LN9 6EP	Deficiencies within the drainage system serving Churchill Avenue, coupled with local topography resulted in surface runoff flowing downhill towards the affected properties, subsequently resulting in internal flooding.	2 Residential	On-going	твс	LCC - Yes Witham 3rd IDB - Yes ELDC - Yes AW - Yes EA - Yes		TBC	ТВС	On-going	твс	твс	твс	TBC	TBC	TBC	TBC	\$19-211	ELDC
27 July 2018	Skegness	Roman Bank - PE25 1RN	Surface water entered the public sewer system following moderate rainfall which resulted in the sewers surcharging leading to internal flooding.	1 Residential	On-going	твс	LCC - Yes AW - Yes Lindsey Marsh IDB - Yes EA - Yes ELDC - Yes	27/02/2020 28/05/2020 26/06/2020	Lindsey Marsh IDB - 01/06/2020 ELDC - 29/06/2020 EA - 02/07/2020	ТВС	On-going	TBC	TBC	TBC	TBC	TBC	ТВС	TBC	\$19-212	ELDC



10/11/2020 Page 1 Duty to Investigate Section 19 Investigations

Section 19 Investig Lincolnshire Count		Investigations - East Lindse	y District Council Network Area - Area Highways Manager Ru	ussell Crockford (E	ast)															
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Date LCC Issued Recommendations to RMA's	Date RMA's Acknowledged Proposed Recommendations	Promoter	Works Status	Estimated Timescales Recommendation	Works Completion Date	LCC / District Council Work Status	EA Work Status	IDB Work Status	Water Company Work Status	3rd Party Work Status	S19 Report File Reference	New Network Area
27 July 2018	Horncastle	West Street - LN9 5AF	Deficiencies in the surface water drainage system resulted in surface water flooding.	1 Residential	On-going	ТВС	LCC - Yes AW - Yes Witham 3rd IDB - Yes EA - Yes ELDC - Yes	16/08/2019	ТВС	ТВС	On-going	твс	твс	твс	TBC	Completed	TBC	TBC	S19-220	ELDC
16 August2018 23 August 2018 27 October 2018	Ingoldmells	Sea Lane - PE25 1PQ	There is evidence to suggest that surface water may have caused flooding as a result of inadequacies in the current surface water drainage arrangement.	8 Commercial	Completed	Task 1 - Consideration be given by LCC Highways, AW and Lindsey Marsh IDB to undertaking a joint drainage investigation.	LCC - Yes AW - Yes Lindsey Marsh IDB - Yes EA - Yes ELDC - Yes	26/02/2020 28/05/2020 26/06/2020	02-Jul-19	TBC	On-going	TBC	Task 1 - TBC	On-going	NA	On-going	On-going	NA	S19-221	ELDC
07 December 2018	Wainfleet	St Johns Street - PE24 4DJ	A highway gully resulted in localised flooding to the adjacent property. The gully in question was poorly maintained, sat within a low spot and served a large impermeable area of highway and roofwater, subsequently, resulting in water ponding and eventual internal property flooding.		Completed	Task 1 - LCC Highways consider undertaking a CCTV survey of the highway drainage system to determine the layour, the discharge location and any faults within the drainage system. Task 2 - LCC Highways consider the installation of additional drainage guillies. Task 3 - LCC Highways consider the installation of dished channel blocks into the footway. Task 4 - LCC Highways consider to resident approval, consider replacing the drop kerb to a full height kerb.	LCC - Yes Lindsey Marsh IDB - Yes ELDC - Yes AW - Yes	26/02/2020 28/05/2020 26/06/2020	LMIDB - 26/02/2020 ELDC - 29/06/2020 LCC - 29/07/2020 AW - 29/07/2020	TBC	On-going	ТВС	Task 1 - TBC Task 2 - TBC Task 3 - TBC Task 4 - TBC	On-going	NA	NA	NA	NA	\$19-222	ELDO
11 June 2019	New Bolingbroke	Main Road - PE22 7JU	TBC	2 TBC	On-going	ТВС	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-223	ELDO
11 June 2019	Skegness	Royal Oak Terrace - PE25 1RN	TBC	3 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-155	ELDO
11 June 2019	Chapel St Leonards	Trunch Lane - PE24 5TU	TBC	1 Commercial	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-166	ELDO
11 June 2019	Utterby	Main Road - LN11 0TP	TBC	1 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-224	ELDO
11 June 2019	Thimbleby	Main Road - LN9 5RE	TBC	1 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-225	ELDO
11 June 2019	Horncastle	Station Yard - LN9 5AG	Internal flooding is believed to have been caused by rainwater ingress from the roof alongside the surcharging of the private drainage system serving the site due to it being unable to outfall into the filver Bain. External flooding at the site also occurred due to the surcharging of Anglian Water foul drainage system, believed to have been caused by rainwater ingress.	1 Commercial	On-going	твс	LCC - Yes AW - Yes Witham 3rd IDB - Yes EA - Yes ELDC - Yes	16/04/2020 14/05/2020 08/06/2020	ТВС	ТВС	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	\$19-227	ELDC
12 June 2019	Partney	Spilsby Road - PE23 4PE	TBC	1 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-229	ELDO
14 June 2019	Alvingham	Lock Road - LN11 7EU	TBC	1 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-235	ELDC
14 June 2019	Goulceby	Butt Lane - LN11 9UP	TBC	1 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-236	ELDC
14 June 2019	Burgh Le Marsh	Storeys Lane - PE24 5LR	TBC	2+ TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-237	ELDC
14 June 2019	Great Steeping	Firsby Road - PE23 5PT	TBC	10+ TBC	On-going	твс	ТВС	TBC	TBC	TBC	On-going	TBC	ТВС	TBC	TBC	TBC	TBC	TBC	S19-240	ELDC
11 June 2019	Kirkby on Bain	Roughton Road - LN10 6YT Main Street - LN10 6YT	Flooding of the five properties was a result of the following factors: surface runoff from developments & highways; overtopping of the River Bain; and a combination of these two factors.	5	On-going	ТВС	LCC = Yes EA = Yes ELDC = Yes Witham 3rd IDB = Yes	27/02/2020 14/05/2020 08/06/2020 29/06/2020	TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-245	ELDC
11 June 2019	Burgh on Bain	Main Road - LN8 6JY	Deficiencies within the highway surface water drainage system coupled with the road / footpath / access alignment enabled and directed surface water flows resulting in internal property flooding.	1 Residential	On-going	Task 1 - Upon the request of ELDC, Ajet attended site and cleaned all the road guillies and jetted all outlets. Ajet also advised of issues with the pipework, which was passed on to LCC Highways.	LCC - Yes Witham 3rd IDB - Yes ELDC - Yes	18/06/2020 29/06/2020	19/06/2020 (ELDC) 01/07/2020 (Witham 3rd IDB)	TBC	On-going	TBC	Task 1 - TBC	ELDC - Complete	NA	TBC	NA	TBC	S19-246	ELDC
11 July 2019	Horncastle	Stanhope Road - LN9 5DG	Internal flooding to 2 properties.	1 Residential 1 Commercial	On-going	твс	твс		твс	твс	On-going	твс	твс	ТВС	TBC	TBC	твс	TBC	\$19-247	ELDC
11 June 2019	Wainfleet All Saints	Matt Pitts Lane - PE24 4LY Brewater Lane - PE24 4LS Spilosy Noad - PE21 NNS Heverside - PE24 4LS AND - PE21 NNS Heverside - PE24 4LS Collison Gate - PE24 4LC Collison Gate - PE24 4LC Warinter Bark - PE24 4LD Mill Lane - PE24 4LB Hattings Drive - PE24 4PX Low Road - PE24 4W Low Road - PE24 AW Low Road - PE24 AW To Lane - PE24 5W Firstly - To Lane - PE24 5W Firstly - Grant - PE25 5NF Partney Grant - PE25 5PJ Grant Steeping - Croft Lane - PE23 5PJ Grant Steeping - Croft Lane - LN2 4.N Croft Bank - Burgh Low Name -	Flooding in this instance occurred from two sources. The main source of flooding was the overtopping of main rivers (The River Steeping) and ordinary watercourses. The second source of flooding was surface water, which resulted in the sucharging of surface and foul water systems. The full report can be found on Lincohshire County Council's webeits using the search terms "Walnifer Flood." Or use the following link https://www.lincohshire.gov.uk/downloads/file/3483/wainfleet-flood-investigation-report	88	Completed	Task 1 - LCC, EA, Partner organisations & IDB's to be a partner in the Steeping Catchment Working Group, contributing to the development of the Action Plan Task 2 - LCC to work through the Emergency Planning & Business Continuity until to support local communities to develop flood plans to become more resilient to flooding: Task 3 - LCC to develop and implement fleasible and value for money flood risk management schemes. Task 4 - EA to utilise the latest asset data acquired through the Creating Asset Management Capacity (CAMC) to target the most appropriate work to the right place;	LCC - Yes EA - Yes Witham Fourth IDB - Yes Black Stulce IDB - Yes Lindsey Marsh IDB - Yes AW - Yes	24/02/2020	03-Mar-2020	ТВС	On-going	TBC	Task 1 - Completed (Date TBC) Task 2 - TBC Task 3 - TBC Task 4 - TBC	On-going	On-going	On-going	On-going	On-going	\$19-248	ELDC
11 June 2019	Horncastle	Stanhope Road - LN9 5DG	Internal flooding to a domestic property.	1 Residential	On-going	твс	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-250	ELDC
25 September 2019	Hainton	Louth Road - LN8 6LX	Heavy rain, as a result of highways runoff redirected down the driveway, causing ponding to the front of the property and resulting in water ingress.	2	On-going	TBC	LCC - Yes Witham 3rd IDB - Yes	17/07/2020	Witham 3rd IDB - 17/07/2020	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-255	ELDC
27 September 2019	Burgh Le Marsh	Church Street - PE24 5LB	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-264	ELDC
June/July 2019	Croft Bank	Croft Bank - PE24 4RJ	Internal flooding to basement in a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-267	ELDC
08 October 2019	Chapel St Leonards	St Leonards Drive - PE24 5RF	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-269	ELDC



 ∞

Duty to Investigate Section 19 Investigati

Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East) EA Work Status IDB Work Status Date of Incident Street / Road Name Description of Flooding Works Status Surface water flooding is believed to have resulted from several consecutive small magnitude rainfall events ocupled with restricted discharge to the surface water arrange system caused by paralla blockage of the highway guilles on Anhort Lane and those of the private drainage system of the property and adjacent car park. This besequently resulted in water ponding in the low point of the car park, until water levels exceeded the threshold of the kerbs flowing straight into the property. Task 1 - TBC Task 2 - TBC Task 3 - TBC 09 October 2019 27 August 2016 On-going ELDC Ingoldmells On-going 13 August 2019 Main Road - LN11 7RZ 1 Residential TBC S19-272 TBC 15 October 2019 Chapel St Leonards St Leonards Drive - PE24 5RF Internal flooding to a domestic property. 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC S19-277 ELDC 26 October 2019 Hoop End - DN36 5LB 1 Residential TBC S19-281 St Edith Gate - LN11 8SS Manby Middlegate - LN11 8SU 26 October 2019 Grimoldby Internal flooding to 1 domestic property and 1 commercial property. + TBC (1 commercia On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-282 ELDC TBC TBC 26 June 2019 Greetham Main Road - LN9 6NT 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC S19-285 ELDC Internal flooding to a domestic property. Padleys Lane - PE23 4AP On-going TBC TBC TBC TBC TBC TBC TBC S19-311 14 November 2019 Witham Road - LN10 6RW Internal flooding to one commercial property. 1 Commercial On-going TBC TBC TBC On-going TBC TBC TBC TBC TBC S19-333 20 November 2019 Lumley Road - PE25 3NG 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-336 TBC 1 Residential TBC S19-350 ELDC 14 January 2020 Coningsby Reedham Lane - LN4 4RX Internal flooding to one domestic property. On-going On-going 15 January 2020 Coningsby High Street - LN4 4RA Internal flooding to one domestic property. 1 Place of Worship On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-351 ELDC TBC TBC TBC 20 January 2020 Armtree Road - PE22 7AQ TBC On-going TBC S19-352 Langrick A blocked drain (covered by road surfacing) causing internal flooding to propertie On-going 18 February 2020 Lincoln Road - LN9 5AW 1 Residential TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-369 Horncastle Internal flooding to property On-going On-going 08 July 2019 Church Lane - PE23 4LP TBC TBC On-going On-going 29 July 2020 Louth Eastgate - LN11 9PG TBC 1 TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-417 ELDC 28 August 2020 Skegness Roman Bank - PE25 2RU TBC 2 TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-425 25 September 2020 Skegness Roman Bank - PE25 2RU TBC 1 TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-427 ELDC 25 September 2020 Trefoil Drive - PE25 2LE TBC 1 TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-428



Duty to Investigate
Section 19 Investigations
Lincolnshire County Council Section 19 Investigations - North Kesteven District Council & South Kesteven District Council Network Area - Area Highways Manager Rowan Smith (West) Date LCC Issued Recommendations to RMA's Date RMA's Acknowledged IDB Work Status EA Work Status LCC - Yes Witham 1st IDB - Yes NA NA 28 June 2012 North Street - LN4 3LY 12 September 2012 LCC Witham 1st IDB Ongoing Ongoing Ongoing S19-048 Task 1 - 2012 Task 2 - TBC Task 3 - TBC Task 4 - TBC Task 5 - TBC Task 6 - TBC Task 7 - TBC Task 8 - TBC EA - Yes AW - Yes LCC - Yes NA NA 28 June 2012 Digby Beck Street - LN4 3NE 12 September 2012 On-going Ongoing Ongoing Ongoing S19-048 28 June 2012 On-going NA NA S19-048 NKDC & SKDC 12 September 2012 Ongoing Ongoing Ongoing Digby Sleaford Road - LN4 3SL Hallams Lane - LN4 3RY Church Lane - LN4 3SB Thorpe Tilney / Timberland Feasibility 2017/18 Possible works 2019/20 28 June 2012 28 November 2012 On-going On-going On-going On-going Task 1 - TBC Task 2 - TBC On-going On-going NA NA S19-056 NKDC & SKDC 06 July 2012 West End - NG34 0JL 14 December 2012 On-going On-going Swaton Task 1 - TBC Task 2 - TBC NA NKDC & SKDC 06 August 2012 Caythorpe 19 December 2012 On-going Summer 2016 On-going NA End 2015 Task 1 - TBC NKDC & SKDC Corby Glen 4 August 2014 On-going On-going Task 1 - Property owner advised on preventative measures to protect the property.

Task 2 - Welland & Deeping IDb consider repairing the identifield blockage diversion to their system. 22 May 2014 Market Deeping Market Place - PE6 8EA 20 August 2014 Task 1 - March 2017 Task 2 - TBC Task 3 - March 2017 Task 4 - March 2017 Task 5 - March 2017 Task 6 - Completed (Date TBC) 28 August 2015 14 September 2015 04-May-16 LCC EA On-going On-going NA NA On-going Task 3 - EA considers installation of a trash screen.

Task 4 - The EA considers investigating the possible construction of a storage lagoon in association with SKDC & LCC.

Task 5 - The EA considers the complete replacement of the Rackhams Yard Cubert to increase its capacity.

Task 6 - Consideration be given to not adopting the unadopted section of this continuation. NA NA NA S19-144

Duty to Investigate Section 19 Investigate incolnshire County Council Section 19 Investigations - North Kesteven District Council & South Kesteven District Council Network Area - Area Highways Manager Rowan Smith (West) Date LCC Issued Recommendations to Water Company Work Status

Work Status

Work Status

S19 Report
File Reference Date RMA's Acknowledged EA Work Status IDB Work Status Works Completion Date NA 04 July 2015 Bainton Road - PE9 4RT LCC - Yes AW - Yes 19/11/2015 19 November 2015 On-going On-going NA On-going NA S19-129 NKDC & SKDC property.

Task 6 - LCC to carry out a program of gully cleaning. Task 1 - There is a further investigation undertaken to determine possible overland flow, paths and storage areas.

Task 2 - Include potential flood attendion scheme in the Medium Term Pit Task 2 update - an outline business case is currently being developed will works being planned for 2021/2022.

Task 3 - AW have cleansed their surface water sewers. Task 1 - TBC Task 2 - TBC kk 3 - Complete (D TBC) 24 August 2015 Long Bennington On-going S19-137 NKDC & SKDC Task 1 - LCC cleansed the culvert under the road in July 2019 and identified defects in connecting iparian systems.

Task 2 - Further investigations into the highway drainage should be made to ensure it is adequate. TBC NA NA NA 14 June 2016 Woolsthorpe by Belvoir LCC - Yes S19-178 NKDC & SKDC 15 June 2016 South Witham Great Close - NG33 5QH Internal flooding to property TBC TBC On-going TBC TBC TBC TBC TBC TBC S19-173 NKDC & SKDC Task 1 - A capital scheme has been identified and is included in the national Task 2 - Consideration be given to identifying the ownership of the existing inference of the capital scheme of the capital scheme of the capital scheme of the existing interest of the existing translation to give the capital scheme of the existing translations with one that will provide security, minimise maintenance requirements and allow water to flow into the culverted vatercourse with minimal restriction.

Task 4 - Consideration be given to altering the existing configuration of the culverted vatercourse.

Task 5 - LCC considers sintereprohibities. Task 1 - TBC
Task 2 - Complete
(Date TBC)
Task 3 - TBC
Task 4 - TBC
Task 5 - Complete
(Date TBC)
Task 6 - TBC
Task 6 - TBC
Task 8 - TBC LCC - Yes Welland & Deeping IDB - Yes Black Sluice - Yes AW - Yes SKDC - Yes NA NA 14 June 2016 On-going 2024/25 NA S19-170 NKDC & SKDC Bourne Beech Avenue - PE10 9RR 8 May 2018 LCC On-going On-going LCC = Yes Welland & Deepings IDB - Yes 14 June 2016 Edenham Road - PE10 OLG 8 May 2018 NA NA S19-194 LCC - Yes AW - Yes Upper Witham IDB - Yes EA - Yes NKDC - Yes Main Road - LN5 0QB/ LN5 0PY High Street - LN5 OPN TBC TBC TBC TBC S19-202 NKDC & SKDC 02 June 2018 On-going 02/07/2020 - EA On-going Indications are that riparian systems had a significant impact on the hydraulic performance of the surface water drainage in the area, including highway drainage impounded by local topography. This led to the systems being overwhelmed durin heavy rain resulting in flooding to property. Task 1 - TBC Task 2 - TBC 04 June 2018 Brant Broughton High Street - LN5 0SA On-going LCC On-going TBC TBC NA S19-205 NKDC & SKDC 01/07/2020 - WFIDB 02/07/2020 - EA avy rainfall coupled with deficiencies in the highways surface water drainage systems. resulted in surface water flooding. Church Lane - NG32 2AP On-going TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-208 NKDC & SKDC On-going TBC TBC NA S19-218 NKDC & SKDC 13 August 2018 High Street - LN5 0SL Brant Broughton On-going Jerusalem Road - LN6 5TW 1 TBC TBC TBC TBC TBC S19-049 NKDC & SKDC On-going On-going 1 TBC TBC TBC TBC TBC TBC S19-232 NKDC & SKDC 14 June 2019 Jerusalem - LN6 4RN TBC On-going TBC TBC TBC TBC TBC TBC Skellingthorpe On-going 14 June 2019 High Street - LN5 0DZ 1 TBC TBC TBC TBC TBC TBC TBC S19-234 NKDC & SKD0 TBC TBC 07 May 2019 Billinghay Tattershall Road - LN4 4DD On-going TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC S19-257 NKDC & SKDC 27 July 2019 Old Haddington Road - LN5 9FN TBC TBC TBC TBC TBC TBC June 2019 11/10/2019 Brant Road - LN5 9AF On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-259 NKDC & SKDC The initial cause of flooding appears to be rainfall falling on the carriageway an adjacent land, flowing to a low point in the highway. This was exacerbated by feliclicancies in the highway drainage system (flotched drains) and high groundw vels, which increased surface runoff from adjacent land and potentially increase quantity of sill tendering the drainage system. TBC TBC 01 October 2019 On-going TBC TBC TBC TBC TBC TBC NKDC & SKD0 28 September 2019 Brant Broughton High Street - LN5 0SL Internal flooding to a commercial property. On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-262 NKDC & SKDC TBC TBC TBC S19-270 NKDC & SKDC 12 August 2019 Digby North Street - LN4 3LY 1 Residential On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC Internal flooding to a domestic property. TBC TBC TBC Tom Lane - NG34 8QW Internal flooding to 1 school property. On-going

Duty to Investigate Section 19 Investiga	ations																			
Lincolnshire County	Council Section 19 Investi	igations - North Kesteven District	Council & South Kesteven District Council Network Area - Area			Smith (West)	Risk Management Authorities with	Date LCC Issued	Date DMA's Astronomical and			Father and Times and In-	Waster Commission	LCC / District	FA West	IDD Wards	Water	2-d Posts	C40 Provide	
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Responsibilities and whether they are exercising functions	Recommendations to RMA's	Date RMA's Acknowledged Proposed Recommendations	Promoter	Works Status	Estimated Timescales Recommendation	Works Completion Date	Council Work Status	EA Work Status	IDB Work Status	Company Work Status	3rd Party Work Status Fi	S19 Report file Reference	New Network Area
09 August 2019	Sleaford	Southgate - NG34 7RR	Internal flooding to a 1 commercial property.	1 Commercial	On-going	твс	твс		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-276	NKDC & SKDC
29 October 2019	South Kyme	South Parade - LN4 4AQ	Internal flooding to 5 domestic properties.	5 TBC	On-going	ТВС	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-283	NKDC & SKDC
November 2019 (*3)	Metheringham	Lincoln Road - LN4 3EF	High groundwater levels due to heavy rainfall resulted in internal property fooding.	1 Residential	On-going	Task 1 - LCC to undertake local repair to cuked, and jetting the system dwinteream to provide an unimpeded discharge. Task 2 - LCC to relay cukent to discharge to the AWS surface water sever on The Horsenberg (e.a. AWH	LCC - Yes AW - Yes	02/07/2020	02/07/2020 - EA Witham First IDB - 15/07/2020 / 03/08/2020 LCC - 29/07/2020 NKDC - 29/07/2020 AW - 29/07/2020	LCC AW	On-going	TBC	Task 1 - TBC Task 2 - TBC Task 3 - TBC	TBC	NA	NA	TBC	NA	S19-291	NKDC & SKDC
05 November 2019	North Rauceby	Tom Lane - NG34 8QW	Internal flooding to one commercial property.	1 Commercial	On-going	твс	твс		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-292	NKDC & SKDC
07 November 2019	North Rauceby	Tom Lane - NG34 8QW	Internal flooding to one commercial property.	1 Commercial	On-going	твс	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-294	NKDC & SKDC
07 November 2019	Sudbrook	Carlton Road - NG32 3SE	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-296	NKDC & SKDC
14 October 2019 26 October 2019 07 November 2019	Sedgebrook	Village Street - NG32 2EN	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	твс	TBC	TBC	TBC	TBC	TBC	TBC	S19-299	NKDC & SKDC
07 November 2019	Brandon	Church Lane - NG32 2AP	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-300	NKDC & SKDC
07 November 2019	Dorrington	Sleaford Road - LN4 3PU	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-301	NKDC & SKDC
07 November 2019	Scopwick	Main Street - LN4 3NR	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-302	NKDC & SKDC
07 November 2019	Stapleford	Brecks Lane - LN6 9LA	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-303	NKDC & SKDC
07 November 2019	Swinderby	High Street - LN6 9LW	Internal flooding to one commercial property.	1 Commercial	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-304	NKDC & SKDC
08 November 2019	Waddington	Darwin Close - LN5 9GB	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-308	NKDC & SKDC
14 November 2019	Sleaford	Southgate - NG34 7RR	Internal flooding to one commercial property.	1 Commercial	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-328	NKDC & SKDC
15 November 2019	Claypole	Tinsley Close - NG23 5BS	Internal flooding to one domestic property.	1 Residential	On-going	TBC	твс		ТВС	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-330	NKDC & SKDC
14 November 2019	Stragglethorpe	Stragglethorpe Lane - LN5 0QZ	A series of prolonged rainfall events resulted in exceptionally high river levels, which due to the areas geology, influenced local groundwater levels via flow transference. This high groundwater level, combined with the capability of local drainings eystems is considered to have contributed to flooding at the property.	1 Residential	On-going	твс	LCC - Yes Upper Witham IDB - Yes EA - Yes NKDC - Yes		TBC	TBC	TBC	TBC	ТВС	TBC	TBC	TBC	TBC	TBC	S19-332	NKDC & SKDC
14 November 2019	Claypole	Tinsley Close - NG23 5BS	Internal flooding to two domestic properties.	2 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-335	NKDC & SKDC
16 November 2019	Heighington	High Street - LN4 1JS	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-338	NKDC & SKDC
27 November 2019	Scopwick	Main Street - LN4 3NW	Heavy rainfall coupled with the hydrological overloading of the riparian culverted watercourse resulted in surcharging and overfowing of the open watercourse section. Discharge then entered the property through the external door at the lowest point.	1 Residential	Completed	Task 1 - Consider undertaking a full CCTV survey of the culverted section. Task 2 - Subject to the findings of the CCTV survey, then consideration be given to repair/replacement works, as appropriate, including construction of a valved headwall at outfall of culvert.	LCC - Yes AW - Yes	20/05/2020	29/09/2020	TBC	On-going	твс	Task 1 - TBC Task 2 - TBC	On-going	NA	NA	NA	NA	S19-341	NKDC & SKDC
11 November 2019	Aslackby	Kirkby Underwood Road - NG34 0HH	Internal flooding to one domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-343	NKDC & SKDC
02 December 2019 15 February 2020 16 February 2020	Normanton	Main Street - NG32 3BH	Internal flooding to one commercial property.	1 Commercial	On-going	твс	твс		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-344	NKDC & SKDC
02 December 2019	Blankney Fen	Blankney South Drove - LN10 6XH	Internal flooding to one commercial property.	1 Commercial	On-going	твс	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-345	NKDC & SKDC
28 November 2019	Scopwick	Main Street - LN4 3NR	Internal flooding to one domestic property.	1 Residential	On-going	твс	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-346	NKDC & SKDC
November 2019 (*3)	Metheringham	Lincoln Road - LN4 3EF	High groundwater levels due to heavy rainfall resulted in internal property flooding.	1 Residential	On-going	Task 1 - LCC to undestake local repair to culvert, and jetting the system downstream to provide an unimpeded discharge. Task 2 - LCC to relay culvert to discharge to the AVRS surface water sewer on 'The Horseshoes' (ex. AVMH 6559). Task 3 - LCC to relaying culvert through to a suitable outfall point on High Street, and any associated jetting of the existing downstream system to provide unimpeded discharge.	LCC - Yes AW - Yes	02/07/2020	02/07/2020 - EA Witham First IDB - 15/07/2020 / 03/08/2020 LCC - 29/07/2020 NKDC - 29/07/2020 AW - 29/07/2020	LCC AW	On-going	TBC	Task 1 - TBC Task 2 - TBC Task 3 - TBC	TBC	NA	NA	TBC	NA	S19-347	NKDC & SKDC
20 December 2019	Claypole	Tinsley Close - NG23 5BS	Internal flooding to a domestic property.	1 Residential	On-going	твс	TBC		TBC	TBC	On-going	твс	TBC	TBC	TBC	TBC	TBC	TBC	S19-349	NKDC & SKDC
07 February 2020	Digby Fen	Fen Road - LN4 4DT	Internal flooding to one property.	1 Commercial	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-362	NKDC & SKDC
TBC	North Scarle	Chapel Lane - LN6 9EX	Internal flooding to one property.	1 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-364	NKDC & SKDC
14 February 2020	Welbourn	High Street - LN5 0NH	internal flooding to property	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-368	NKDC & SKDC
17 February 2020	Stragglethorpe	Stragglethorpe Lane - LN5 0QZ	A series of prolonged rainfall events resulted in exceptionally high river levels, which due to the areas geology, influenced local groundwater levels van flow the Theodore (This high groundwater level, combined with the capability of local drainage systems is considered to have contributed to flooting at the property.	1 Residential	On-going	твс	LCC - Yes Upper Witham IDB - Yes EA - Yes NKDC - Yes		TBC	TBC	TBC	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-332	NKDC & SKDC
16 February 2020	Long Bennington	The Maples - NG23 5FP	Internal flooding to one residential property	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-372	NKDC & SKDC
16 February 2020	Long Bennington	Church Street - NG23 5ES	Internal flooding to one residential property	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-373	NKDC & SKDC

Duty to Investigate Section 19 Investigate	Investigate 19 Investigations 19 Investigations - North Kesteven District Council & South Kesteven District Council Network Area - Area Highways Manager Rowan Smith (West) Fire Council Section 19 Investigations - North Kesteven District Council & South Kesteven District Council Network Area - Area Highways Manager Rowan Smith (West)																			
Lincolnshire County	Council Section 19 Investig	gations - North Kesteven District	Council & South Kesteven District Council Network Area - Are	a Highways Ma	ınager Rowan	Smith (West)														
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Date LCC Issued Recommendations to RMA's	Date RMA's Acknowledged Proposed Recommendations	Promoter	Works Status	Estimated Timescales Recommendation	Works Completion Date	LCC / District Council Work Status	EA Work Status	IDB Work Status	Water Company Work Status	3rd Party Work Status	S19 Report File Reference	New Network Area
18 February 2020	Dry Doddington	Clensey Lane - NG23 5HT	Internal flooding to one residential property	1 Residential	On-going	твс	ТВС		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-374	NKDC & SKDC
17 February 2020	Grantham	Denton Avenue - NG31 7JE	Internal flooding to one property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-375	NKDC & SKDC
24 February 2020	Carlton Scroop	Main Road - NG32 3AZ	Internal flooding to property	TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-376	NKDC & SKDC
28 February 2020	Grantham	Hazelwood Drive - NG31 8GZ	Internal flooding to one property.	TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-377	NKDC & SKDC
15 February 2020	Long Bennington	Main Road - NG23 5DJ	Internal flooding to one property.	1 Residential	On-going	твс	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-378	NKDC & SKDC
17 June 2020	Washingborough	Royal Oak Lane - LN4 1AX	Internal flooding to one residential property	1 residential TBC	On-going	TBC	TBC		TBC	TBC	on-going	TBC	TBC	TBC	твс	TBC	TBC	TBC	S19-409	NKDC & SKDC
16 August 2020	Heckington	New Street - NG34 9JL	ТВС	твс	On-going	твс	TBC		TBC	TBC	On-going	твс	TBC	TBC	твс	TBC	TBC	TBC	S19-415	NKDC & SKDC
17 August 2020	Bassingham	High Street - LN5 9JZ	TBC	TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-418	NKDC & SKDC
17 August 2020	Sleaford	Southgate - NG34 7RY	TBC	TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-419	NKDC & SKDC
17 August 2020	Grantham	North Street - NG31 6NU	TBC	твс	On-going	твс	TBC		TBC	TBC	On-going	твс	TBC	TBC	твс	TBC	TBC	TBC	S19-421	NKDC & SKDC
19 August 2020	Walcot	Pickworth Road - NG34 0SS	TBC	твс	On-going	TBC	TBC		TBC	TBC	On-going	твс	TBC	TBC	ТВС	TBC	TBC	TBC	S19-423	NKDC & SKDC

Section 19 Investiga Lincolnshire County	ations Council Section 19 Inve	stigations - Boston Borough Cou	ncil & South Holland District Council Network Area -	Area Highways	Manager Kyra Ne	ettle (South)		T												
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Date LCC Issued Recommendations to RMA's	Date RMA's Acknowledged Proposed Recommendations	Promoter	Works Status	Estimated Timescales Recommendation	Works Completion Date	LCC / District Council Work Status	EA Work Status	IDB Work Status	Water Company Work Status	3rd Party Work Status	S19 Report File Reference	New Network Area
06 July 2012	Donington	Quadring Road - PE11 4TB	Heavy riainfall exceeded the capacity of the local drainage network resulting in internal flooding.	1 Residential	Completed	Task 1 - LCC consider continuing their investigation of both the carriageway and footway surface water drainage system. Task 2 - AW consider investigating the capacity and performance of their combined sewerage system.	LCC - Yes AW - Yes		10 December 2012	NA	On-going	ТВС	Task 1 - TBC Task 2 - TBC	On-going	NA	NA	On-going	NA	S19-039	BBC & South Holland
10 June 2016	Deeping St Nicholas	Coronation Avenue - PE11 3EP	The exact cause of the flooding incident is uncertain. It may however, have been a result of imadequacies in the South Holland District Council drainage infrastructure, the Lot Charage infrastructure, the very significant storm event in excess of design capacity or a combination of two or all three of these possible causations.	3 Residential	Completed	Task 1 - Consideration be given to the construction of inspection chambers on line of the existing highway carrier drain by LCC Highways. Task 2 - Consideration be given to the jetting of the highways system and the undertaking of a CCTV survey by LCC Highways. Task 3 - A hydraulic check of the drainage system be considered by LCC Highways. Task 4 - An investigation of the combined sewer be considered by SHDC to ascertain the connectivity and thereby estimate flows through the system, along with a hydraulic check against theoretical capacity.	LCC - Yes Welland & Deeping IDB - Yes SHDC - Yes	28/08/2018	11 October 2018	TBC	On-going	TBC	Task 1 - TBC Task 2 - TBC Task 3 - TBC Task 4 - TBC	On-going	NA	NA	NA	NA	S19-138	BBC & South Holland
16 June 2016 27 August 2016	Spalding	Mallard Road - PE12 6ND Weston Hills Road - PE12 6NE	The possible causation of the flooding is complex, involving different factors (both drainage and development issues), within defined subcatchments.	7 Residential 1 Commercial	Completed	Task 1 - LCC and SHIDB are working in partnership to investigate and identify potential improvements to the surface water duringe in the local area. Task 2 - RIMAs consider informing ripartial inal/owners of the findings of the study and provide recommendations for returning the watercourses to a servicable state. Task 3 - RIMAs consider exploring the option to the Fulley Roads Management Company to take on stuture maintenance of the ripartian watercourses. Task 4 - South Holland IDS consider what improvements would be required to the watercourse for adoption Task 5 - RIMAs consider conforming that the watercourse on the north side of Weston Hill Road is of full rigination covered in the state of the state of the cross connection between the ripartian vatercourse on Weston Hill Road and South Holland IDS scheduled Austendyke West Drain. Task 7 - RIMAs consider determining responsible for maintenance of the udverted watercourse on Kelet Task 8 - RIMAs consider determining responsible for maintenance of the udverted watercourse on Kelet Task 9 - RIMAs consider determining responsible for maintenance of the udverted watercourse on Kelet Task 9 - RIMAs consider determining responsible for maintenance of the udverted watercourse on Kelet Task 9 - SIMAs consider determining the counter and South Holland RIMA let Mile Oyse. Task 9 - SIMAs consider reviewing all horticultural holdings within the area within the Study Area where significant impermeable structures have been built, in particular to holck for compliance with the approved planning application.	LCC - Yes South Holland IDB - Yes SHDC - Yes EA - Yes		11 October 2018	LCC South Holland IDB	On-going	2020/21	Task 1 - TBC Task 2 - 29/09/2019 Task 3 - Completed (Date 1 - Completed (Date 1 - Completed (Date 1 - Completed (Date 2 - Completed (Date 3 - Comp	On-going	NA	On-going	NA	NA	\$19-185	BBC & South Holland
28 June 2017	Kirton	London Road - PE20 1JA	Surface water runoff from the highway resulted in internal flooding. This was complemented by capacity issues within the soukaways serving the properties alongside capacity issues of the highway drainage system.	1 Residential	Completed	Task 1 - LCC Highways consider identifying the extent of and undertaking action to both remove non highway discharge from the highway system and divert it into a suitable alternative. Task 2 - LCC Highways consider identifying and inspecting the culverts that serve the highway discharge system with any deficiencies being rectified. Task 3 - LCC Highways consider upgrading the highway diamage system. Task 4 - LCC Highways consider upgrading the highway diamage system.	BBC = Yes Black Stuice IDB = Yes LCC = Yes AW = Yes EA = Yes		TBC	TBC	On-going	твс	Task 1 - TBC Task 2 - TBC Task 3 - TBC Task 4 - TBC	On-going	NA	NA	NA	NA	S19-189	BBC & South Holland
20 July 2017	Tydd St Mary	Church Way - PE13.5QY	During heavy rainfall, property roof runoff discharged onto an uneven pavement which acted as a channel, subsequently, directing the flow towards the property.	1 Residential	Completed	Task 1 - LCC Highways consider the reprofiling of the path around the down water pipe. Task 2 - LCC Highways consider the installation of a channel from the down pipe towards the highway. Task 3 - LCC Highways consider jetting and clearing all highways guilles in the area. Task 4 - LCC Highways considers the construction of in-line inspection chambers on the highway surface water drain.	LCC - Yes South Holland IDB - Yes AW - Yes		11 October 2018	TBC	On-going	TBC	Task 1 - TBC Task 2 - TBC Task 3 - TBC Task 4 - TBC	On-going	NA	NA	NA	NA	S19-191	BBC & South Holland
24 January 2018	Swineshead	Coles Lane - PE20 3NS	Surface or ground water entered the AW foul system causing it to surcharge, flooding the adjacent highway. There is no clear evidence to suggest that surface water caused internal property flooding.	1	Completed	Task 1 - AW consider undertaking further investigations into their foul sewage network.	LCC - Yes AW - Yes Black Slucie - Yes EA - Yes BBC - Yes	17th December 2018		TBC	On-going	твс	Task 1 - TBC	NA	NA	NA	On-going	NA	S19-200	BBC & South Holland
13 August 2018	Kirton	Station Road - PE20 1EE	Rainfall overwhelmed the surface water drainage system, resulting in the ponding of water, which ultimately flooded three properties.	1 Residential 2 Commercial	Completed	Task 1 - The Relevant RMAs consider following through with the recommendations proposed in S19- 169. Task 1 update (06/11/2020) - LCC and Black Sluice IDB are working together to deliver the recommendations identified in S19-169. Task 2 - LCC consider commencing a protect and surveying systems to confirm possible discharge points of a surface water drainage system.	LCC - Yes BBC - Yes Black Stuice IDB - Yes AW - Yes	18th December 2018	May-2019	TBC	On-going	ТВС	Task 1 - TBC Task 2 - TBC	On-going	NA	On-going	On-going	NA	S19-217	BBC & South Holland
12 June 2019	Holbeach	Battlefields Lane South - PE12 7PQ	ТВС	1 TBC	On-going	ТВС	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-228	BBC & South Holland
11 June 2019	Pinchbeck	Brownlow Crescent - PE11 3XD	Heavy rainfall exceeded the capacity of the drainage system serving Brownlow Crescent, which itself was limited due to sitation. This was further exacerbated by deficiencies within the adjoining internal Drainage Board drain. Consequently, resulting in surface water flooding. Fortunately no internal property flooding occurred.	0	On-going	TBC	EA = Yes Welland & Deeping IDB = Yes South Holland IDB = Yes AW = Yes LCC = Yes SHDC = Yes	27/02/2020 08/06/2020 29/06/2020	29/07/2020	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-050	BBC & South Holland
11 June 2019	Kirton	King Street - PE20 1HZ	твс	1 TBC	On-going	твс	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-161	BBC & South Holland
11 June 2019	Quadring	St Margarets - PE11 4PR	TBC	1 TBC	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-193	BBC & South Holland
11 June 2019	Spalding	Pinchbeck Road - PE11 1QF	Flooding is believed to be caused by groundwater entering the properties basements.	2	On-going	твс	EA = Yes Welland & Deeping IDB = Yes South Holland IDB = Yes AW = Yes LCC = Yes SHDC = Yes	27/02/2020 08/06/2020 29/06/2020	29/07/2020	твс	On-going	твс	TBC	TBC	TBC	твс	TBC	TBC	S19-226	BBC & South Holland
12 June 2019	Wrangle	Main Road - PE22 9AT	TBC	3 TBC	On-going	ТВС	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-231	BBC & South Holland
14 June 2019	Spalding	St Thomas Road - PE11 2TJ	Heavy rainfall exceeded the capacity of the highways surface water drainage system, due to sillation. This in turn caused the system to surcharge, which flooded low lying properties.	2	On-going	твс	EA = Yes Welland & Deeping IDB = Yes South Holland IDB = Yes AW = Yes LCC = Yes SHDC = Yes	27/02/2020 08/06/2020 29/06/2020	29/07/2020	твс	On-going	твс	TBC	TBC	TBC	твс	TBC	TBC	S19-238	BBC & South Holland
14 June 2019	Boston	Paddock Grove - PE21 8QL	Groundwater flooding possibly augmented by surface or rainfall flow is believed to have resulted in internal flooding.	1 Residential	On-going	ТВС	LCC = Yes AW = Yes Black Sluice IDB = Yes EA = Yes BBC = Yes	27/02/2020 04/06/2020 26/06/2020	16/04/2020 - EA	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-239	BBC & South Holland
14 June 2019	Spalding	Stonegate - PE11 2PP	The affected properties suffered from groundwater flooding.	2	On-going	ТВС	EA = Yes Welland & Deeping IDB = Yes South Holland IDB = Yes AW = Yes LCC = Yes SHDC = Yes	27/02/2020 08/06/2020 29/06/2020	29/07/2020	TBC	On-going	ТВС	TBC	TBC	TBC	TBC	TBC	TBC	S19-241	BBC & South Holland
14 June 2019	Spalding	Neville Avenue - PE11 2EH	The cause of flooding on Neville Avenue is possibly three fold: Surcharging of the Anglian Water foul water system; Surface water exceedance from highway drains; and Riparian watercourse in- operable in-effective from lack of maintenance/neglect or possible loss of outfall.	3	On-going	твс	EA = Yes Welland & Deeping IDB = Yes South Holland IDB = Yes AW = Yes LCC = Yes SHDC = Yes	27/02/2020 08/06/2020 29/06/2020	29/07/2020	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-242	BBC & South Holland
11 June 2019 14 June 2019	Spalding	St Andrews Road - PE11 2SH Wentworth Close - PE11 2SN	Heavy rainfall exceeded the capacity of the highways surface water drainage system, due to sitiation. This was further exacerbated by an ineffective riparian waterourse. Consequently, causing flooding to low lying properties, predominately garages and non-trailed spaces. Fortunately, no internal property flooding occurred.	0	On-going	ТВС	EA = Yes Welland & Deeping IDB = Yes South Holland IDB = Yes AW = Yes LCC = Yes SHDC = Yes	27/02/2020 08/06/2020 29/06/2020	29/07/2020	TBC	On-going	ТВС	TBC	TBC	TBC	TBC	TBC	TBC	S19-243	BBC & South Holland
28 August 2019	Wrangle	Main Road - PE22 9AD	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	TBC	TBC	TBC	TBC	TBC	TBC	TBC	S19-249	BBC & South Holland
14 August 2019	Old Leake	Station Road - PE22 9QQ	Internal flooding to a domestic property.	1 Residential	On-going	TBC	TBC		TBC	TBC	On-going	твс	твс	TBC	TBC	TBC	TBC	TBC	S19-256	BBC & South Holland



Duty to Investigate
Section 19 Investigations
Lincolnshire Council Section 19 Investigations - Boston Borough Council & South Holland District Council Network Area - Area Highways Manager Kyra Nettle (South) Water Company Work Status BBC & South Holland 28 September 2019 Old Leake School Lane - PE22 9NJ TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-261 BBC & South Holland 01 October 2019 Bridge Road - PE12 9UA TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-263 Sutton Bridge 1 Commercial On-going On-going BBC & South TBC TBC TBC 15 October 2019 The Drayton - PE20 3JN On-going TBC On-going TBC TBC TBC TBC TBC TBC S19-274 BBC & South Holland Coles Lane - PE20 3NS TBC TBC TBC TBC TBC TBC TBC TBC TBC S19-278 15 October 2019 1 residential On-going On-going TBC Internal flooding to a domestic property. TBC TBC TBC 17 October 2019 Hoffleet Stow Hoffleet Road - PE20 3AJ Internal flooding to a domestic property. 1 Residential On-going TBC TBC TBC On-going TBC TBC TBC TBC TBC S19-279 BBC & South Holland 15 October 2019 TBC TBC TBC TBC TBC TBC TBC TBC Spalding Little London - PE11 2UE Internal flooding to a 1 commercial property. On-going TBC On-going TBC S19-280 BBC & South 4 TBC S19-284 29 October 2019 Surfleet Seas End The Reservoir - PE11 4DJ Internal flooding to 4 domestic properties. On-going TBC TBC On-going BBC & South Holland 29 October 2019 Boston Witham Bank East - PE21 9JU Internal flooding to a domestic property. On-going TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-286 TBC TBC TBC TBC TBC TBC TBC S19-327 14 November 2019 Swineshead Coles Lane - PE20 3NS Internal flooding to one domestic property. 1 Residentia On-going TBC On-going TBC TBC TBC 25 June 2019 Lyndis Walk - PE12 7DF TBC TBC TBC TBC TBC TBC TBC S19-355 BBC & South Holland On-going On-going BBC & South Holland 1 TBC 10 July 2019 Gosberton Spalding Road - PE10 9LE TBC On-going TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-358 BBC & South Holland 11 June 2019 Kirton Station Road - PE20 1EE Internal flooding to one property. 1 TBC On-going TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-359 18 June 2020 Gosberton Salem Street - PE11 4NQ Internal flooding to one residential property. On-going TBC TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-408 BBC & South Holland 12 June 2019 On-going TBC BBC & South Holland 3 TBC TBC TBC 17 August 2020 Kirton TBC On-going TBC TBC TBC TBC On-going TBC TBC TBC TBC TBC S19-416 BBC & South Holland 19 August 2020 Old Main Road - PE12 8LH 1 TBC On-going TBC TBC On-going TBC TBC TBC TBC TBC TBC TBC S19-424 BBC & South Holland 2 TBC S19-426 28 August 2020 Kirton Station Road - PE20 1EE TBC On-going TBC On-going TBC



Open Report on behalf of Andrew Crookham,
Executive Director - Resources

Report to: Flood and Water Management Scrutiny Committee

Date: 30 November 2020

Subject: Flood and Water Management Scrutiny Committee

Work Programme

Summary:

This item enables the Committee to consider and comment on the content of its work programme to ensure that scrutiny activity is focused where it can be of greatest benefit. Members are encouraged to highlight items that could be included for consideration in the work programme.

The work programme will be reviewed at each meeting of the Committee to ensure that its contents are still relevant and will add value to the work of the Council and its partners.

Actions Required:

The Committee is invited to:

- (1) review, consider and comment on the work programme;
- (2) highlight for discussion any additional scrutiny activity which could be included for consideration in the work programme; and note the terms of reference of the Flood and Water Management Scrutiny Committee, as agreed by the County Council.

1. Background

Overview and Scrutiny should be positive, constructive, independent, fair and open. The scrutiny process should be challenging, as its aim is to identify areas for improvement. Scrutiny activity should be targeted, focused and timely and include issues of corporate and local importance, where scrutiny activity can influence and add value.

Overview and scrutiny committees should not, as a general rule, involve themselves in relatively minor matters or individual cases, particularly where there are other processes, which can handle these issues more effectively. All members of overview and scrutiny committees are encouraged to bring forward important items of community interest to the committee whilst recognising that not all items will be taken up depending on available resource.

2. Work Programme

	30 NOVEMBER 2020											
	ltem	Contributor										
1	Investigations undertaken under Section 19 of the Flood and Water Management Act 2010	Paul Brookes, Flood Risk Manager										
2	Environment Agency Update	Morgan Wray, Area Flood and Coastal Risk Manager										

	22 FEBRUARY 2021											
	ltem	Contributor										
1	2020+ Steeping Catchment Action Plan Update	David Hickman, Head of Environment										
2	Innovative Flood and Coastal Resilience Programme	Paul Brookes, Flood Risk Manager										
3	Investigations undertaken under Section 19 of the Flood and Water Management Act 2010	Paul Brookes, Flood Risk Manager										
4	Environment Agency Update	Morgan Wray, Area Flood and Coastal Risk Manager										
5	Anglian Water Update	Jonathan Glerum, Anglian Water										

21 JUNE 2021				
	ltem	Contributor		
1	Induction - Flood Risk Roles and Responsibilities	David Hickman, Head of Environment Paul Brookes, Flood Risk Manager		
2	Introduction to the Role of the Environment Agency	Morgan Wray, Area Flood and Coastal Risk Manager		
3	Introduction to the Role of Anglian Water	Jonathan Glerum, Anglian Water		
4	2020+ Steeping Catchment Action Plan Update	David Hickman, Head of Environment		
5	Investigations undertaken under Section 19 of the Flood and Water Management Act 2010	Paul Brookes, Flood Risk Manager		

	20 SEPTEMBER 2021				
Item		Contributor			
1	Investigations undertaken under Section 19 of the Flood and Water Management Act 2010	Paul Brookes, Flood Risk Manager			
2	Environment Agency Update	Morgan Wray, Area Flood and Coastal Risk Manager			
3	Anglian Water Update	Jonathan Glerum, Anglian Water			

29 NOVEMBER 2021				
	ltem	Contributor		
1	Investigations undertaken under Section 19 of the Flood and Water Management Act 2010	Paul Brookes, Flood Risk Manager		
2	Environment Agency Update	Morgan Wray, Area Flood and Coastal Risk Manager		
3	Anglian Water Update	Jonathan Glerum, Anglian Water		

To Be Scheduled:

Riparian Rights and Responsibilities

3. Conclusion

Members of the Committee are invited to review, consider and comment on the work programme and highlight for discussion any additional scrutiny activity which could be included for consideration in the work programme.

Consideration should be given to the items included in the work programme as well as any 'items to be programmed' listed.

4. Consultation

a) Risks and Impact Analysis

Not Applicable

5. Background Papers

No background papers within Section 100D of the Local Government Act 1972 were used in the preparation of this report.

This report was written by Tracy Johnson, Senior Scrutiny Officer, who can be contacted on 07552 253814 or by e-mail at tracy.johnson@lincolnshire.gov.uk